IBEDA®

SOLUTIONS FOR GASES

Safety Device: ESF-VA

Type ESF-VA for protection of Tapping Points and Distribution Lines

The safety device ESF-VA according to DIN EN ISO 5175-1:

- avoids dangerous gas mixtures by a gas non-return valve (NV)
- stops flashback through flame arrestor (FA)
- a dust filter protects the gas non-return valve against contamination
- every safety device is 100% tested
- all metal components in stainless steel 1.4305 / spring 1.4310

Safety elements of the IBEDA Safety Device ESF-VA:

- NV   Gas non-return valve
- FA   Flame arrestor

Additional features:

- DF   Dust filter

Maintenance:

The safety devices are to be tested by a qualified and authorised person at regular intervals according to country specific regulations. The safety device is to be tested for gas tightness, gas flow and gas return at least once a year.

We would be pleased to offer you the flashback arrestor testing unit model PVGD.

It is not allowed to open the safety devices.

Technical Data:

Gas-Types:	Hydrogen (H) Industrial Gas (C)	Natural Gas (Methane) (M) (P)	Oxygen (O)
Working pressure:	0,30 MPa 3,0 bar	0,50 MPa 5,0 bar	max. 2,0 MPa 20,0 bar
Cracking pressure:	≤ 10 mbar position-independent		
Gas temperature:	-20°C up to +70°C (Oxygen -20°C up to +50°C)		
Ambient temperature:	-20°C up to +70°C		
Threads: EN 560, ISO / TR 28821	3/4 NPT F/F[3)]		3/4 NPT F/F[3)]
Measure and weight:	diameter:	length:	weight:
	55,00 mm	130,00 mm	1458,00 g
Applications:			
Process:	welding	cutting	heating
	up to 30 mm	> 700 mm	> 100 mm

Other materials, surface finishing, gas types and additional connections available on request.
The flashback arrestor meets the test criteria of the Australian standard AS4603:1999

[3)] F = Female, M = Male

CERTIFIED SAFETY - WORLDWIDE!

EN/03/18/00

IBEDA® — SOLUTIONS FOR GASES

Type: **ESF-VA**


## Flow rates [air]:

pv = Primary pressure

ph = Secondary pressure

Δp = Primary pressure minus Secondary pressure

## Conversion Factors:

0,1 MPa = 1 bar = 100 kpa = 14,504 psi

1 m^3/h = 35,31 cu ft/h

	A	H	P	M	M	O	E	L
QG ▶	C_2H_2	H_2	C_3H_8	CH_4+C	CH_4	O_2	C_2H_4	C_3H_6
F	1,2	3,8*	0,90	1,25	1,4	0,95	1,02	0,92

* Conversion factor 2.5 for devices comprising a flame arrestor
  The conversion factor for free flow is 3.8.
  (Reference: BAM report 220, D. Lietze)

Example:

QG = QD x F

QG ▶ A = 6,4 x 1,2 = 7,68 m^3/h C_2H_2

QG = flow / gas type
F = conversion factor
QD = flow / air

Certification/ Technical Standards/ Rules

TRBS German Technical rules for operation safety, DVS German Association for Welding, Cutting and Allied Processes, DGUV German Employer´s liability insurance association rules and regulations.

Standards/ Approvals

Company certified according to
ISO 9001:2015 and ISO 14001:2015,
CE-marking according to: Pressure Equipment Directive 2014/68/EU

(Subject to change without notice)

CERTIFIED SAFETY - WORLDWIDE!

EN/03/18/00